RECOVERED SECTION CORNERS



1) DESCRIPTION: NW COR., SEC. 50, T4S, R4E, G.L.D., ST. HELENA PARISH. (COMMON TO SEC. 27)

FOUND: OLD ROUND CONCRETE MONUMENT BURIED 3" BELOW GROUND. CONCRETE MONUMENT MUST HAVE IRON PIPE OR ROD ENCASED BECAUSE METAL DETECTOR GAVE STRONG SIGNAL BUT NO VISIBLE EVIDENCE OF PIPE OR ROD (09/09/00).

REPORTED BY: DARREL PRIMEAUX, P.L.S.

2) DESCRIPTION: EASTERNMOST COR., SEC. 46, T4S, R4E, G.L.D., ST. HELENA PARISH. (COMMON TO SECS. 50 & 70)

FOUND: SAME CONCRETE MONUMENT AS DESCRIBED ABOVE.

REPORTED: BY DARREL PRIMEAUX, P.L.S.

LOUISIANA DIVISION OF ADMINISTRATION
STATE LAND OFFICE

Public Land Survey Monument Recovery Record
Please use a separate form for each recovered monument

CORNER DESCRITION:
Easternmost corner of Section 46, Township 4S, Range 4E.

___Louisiana Meridian *or* ✓St. Helena Meridian *in* St. Helena Parish, Louisiana.

___Original Monument Found ✓Locally Accepted Monument Found ____Monument Set

List all sections adjacent to this monument.

70
50

Description of original monument and accessories and subsequent restoration (*if known*).
Give sources of information.

MONUMENT DESCRIPTION:
Description of monument and accessories if found:

Old round concrete monument buried 3" below ground. Concrete monument must have iron pipe or rod encased because metal detector gave strong signal but no visible evidence of pipe or rod (09/09/00)
Common to Secs. 50 & 70

Description of monument and accessories if set:

Louisiana State Plane Coordinates of Corner (if determined):
X:_____ Y:_____
Zone:_____ Datum:_____
Coordinates Determined From:
___GPS Survey
___Conventional Survey

SKETCH

REFERENCE MEASUREMENTS (at least three):

Description	Distance	Bearing (Give Basis)

IF MONUMENT WAS SET, METHOD USED TO DETERMIE LOCATION OF LOST CORNER.

SUBMITTED BY: Darrel Primeaux
(*please print*)

DATE: 3-15-2001

Submit To: Louisiana State Land Office
P.O. Box 44124
Baton Rouge, LA 70804-4124

SLO database registration No. SE-S46-T4S-R4E-E

NOTE: **The information contained heron was submitted by the above named Surveyor on a voluntary basis. The State Land Office does not certify that the monument described hereon marks the actual corner it is intended to represent. This information is included in a database that should be used as a research tool only.**